



Full Circle

Braddock Residence

Full Circle
Project of
the Month



We encountered an Ice Dam in late winter of 2019. At first, it looked like a straightforward repair until drywall was removed and revealed wood rot that had been occurring for many years. The scope of the project immediately grew 10x. The wood rot was located in an upstairs bedroom and ran all the way down through a lower bedroom as well. The wall was a common wall going into the garage, so the home had to be effectively braced to restructure the wall.

We called around to a number of area contractors when we realized the project was more than anticipated. Though the timeline for all contractors was pretty far out, Dave was prompt in coming to assess the situation and communicated effectively with us which made us comfortable moving forward with Full Circle. I would recommend to friends and for future projects of my own.

Shannon spearheaded our project with Dave. Cannot say enough about Shannon's work ethic and ability.

This project uncovered a lot of unknown problems

that continually changed the scope of work and made it a very fluid situation. Shannon and Dave never flinched and always were confident in coming up with multiple game plans for my wife and I to discuss and weigh our options. I appreciated them working within our budget, but also being honest about getting the job done right and what it would take to do so.

Dave was especially cognizant of our situation in that we were expecting our first child in October 2019 and one of the rooms being repaired was the nursery. Work was finished in September a month before her due date, which gave us time to finish up paint and decorating for the baby's arrival. Again, it was appreciated.

This was the first job Full Circle has done for us. We would reach out again if we needed anything!



Full Circle Contracting and Home Center

231-627-6535 • 119 North "F" Street, Cheboygan • fullcirlenorth.com

